






# DOE HANFORD SITE - GROUNDWATER QUALITY DATA PLOTS

wellseries-200-299 WELL#=299-E25-2



### VOLATILE ORGANIC COMPOUNDS NO DATA AVAILABLE

### SEMI-VOLATILE ORGANIC COMPOUNDS




WELLNAME=299-E25-2 WELLID=A4766
Well Type=STANDARD Well purpose=GROUNDWATER
Owner=DOE Contact=BHI Well Adv=Compliance=NON-COMPLIANT
Well Construction Date=9/3/1993
X_coor= 575513.80 Y_coor= 136061.90 Datum=NAD83(91) Date Survey= 9/30/1994
Elevation= 206.004 Datum=NAVD88 Date Survey=06/01/94
Ref Point Desc=TOP OF CASING Ref Point side=E Contractor=USACE(JECA)
Total Number of perforation Intervals=2
NPERF#=1 Perf_top= 0.00 Bot= 71.63 m Cas_size= 6.00in Perf_cuts= 0.00 ft
NPERF#=2 Perf_top= 84.12 Bot= 96.32 m Cas_size= 8.00in Perf_cuts= 0.00
























LABORATORY QUALIFIER FLAGS in HEIS are \*, >, B, C, D, E, J, L, P, Q, R, W, X, Y, and Z: Review Document. Main Flags are : J=Estimated value; L=Value between IDL and CRQL (estimated); T=Tentatively identified compound:  
EPA-IGR=EPA-Implementation Guidance for Radionuclides: WAC=Washington Administrative Code:

EXPLANATION: THICK FILLED BARS=Value Above Detection Limit; THIN BARS=Value Below Detection Limit; HATCHED BARS=Value With Data Qualifier Flag

## SEMI-VOLATILE ORGANIC COMPOUNDS













## METALS &amp; PHYSICAL PARAMETERS



## PEST/PCB, HERB, &amp; DIOXINS NO DATA AVAILABLE


## GENCHEM &amp; ORGANICS &amp; GENORGANICS



LABORATORY QUALIFIER FLAGS in HEIS are \*, >, B, C, D, E, J, L, P, Q, R, W, X, Y, and Z: Review Document. Main Flags are : J=Estimated value:L=Value between IDL and CRQL (estimated):T=Tentatively identified compound:  
EPA-IGR=EPA-Implementation Guidance for Radionuclides: WAC=Washington Administrative Code:

EXPLANATION: THICK FILLED BARS=Value Above Detection Limit:THIN BARS=Value Below Detection Limit:HATCHED BARS=Value With Data Qualifier Flag

## GENCHEM &amp; ORGANICS &amp; GENORGANICS



LABORATORY QUALIFIER FLAGS in HEIS are \*, >, B, C, D, E, J, L, P, Q, R, W, X, Y, and Z: Review Document. Main Flags are : J=Estimated value:L=Value between IDL and CRQL (estimated):T=Tentatively identified compound:  
EPA-IGR=EPA-Implementation Guidance for Radionuclides: WAC=Washington Administrative Code:

EXPLANATION: THICK FILLED BARS=Value Above Detection Limit:THIN BARS=Value Below Detection Limit:HATCHED BARS=Value With Data Qualifier Flag